

## EGT Decrease Due To Aircraft Indicating System

EGT Trend on both Engines is on a significantly decreasing trend. The possible cause Pilot Recording Error or aircraft indication system related . Most probable cause is aircraft system related

