

EGT Decrease From An Engine Swap

The EGT system on this aircraft requires troubleshooting to understand and correct the cause of the lower shift noted in the EGT indicating system when the engine was installed on a different aircraft. The problem created by this shift is it places doubt on the accuracy of the EGT indicating system and the ability of the flight crews to identify overtemperature events.

