

Vibration Illustration 1

Case of N1 Vibration caused by Fan Blade lock up. Although the vibration trend was significant the vibration level was well below the AMM recommended guidelines. The Engine operated until a scheduled check where the Fan Blades were removed, lubricated and installed.

