

Creep - Metal Fatigue

This engine is still a problem. If you have eliminated all other issues Borescope is now required. Even though you are not making full rated take off the Creep issue is time and temperature related. The higher the temperature the less operating time it will take to make a permanent set to your turbine components setting the stage for turbine failure. Cruise is at the higher temperature and continues the clock on creep

