

Unstable Cruise Data Recording

Shift was similar for sister engine. One area of concern is capture. Data must be captured only after the engines have stabilized at cruise power for 10 minutes, auto throttles (no power change) off anti ice off.

