

Vibration Illustration 2

N1 Vibration has increased but is still within the guidelines.
However the fan blade annulus fillers seals should be checked
to be sure they are all seated and the , fan blades inspected for
damage

