

Erratic EGT Indicator

EGT indication is Erratic. Most probable cause is loose connection or chaffed lead

